

03-TRAFFIC - LIST OF LOCATIONS

LIST OF ROUTE SEGMENTS

Route	City/Town	Segment Mile points	Type of Work	Mill Depth	Patching	Crack Filling	HMA S0.5 Traffic Level 2 (Overlay)	HMA S0.25 Traffic Level 2 (Overlay)	HFST Curb to Curb	HFST Shoulder to Shoulder	Aggregate on EOR Drop offs	Start Lat/Long	End Lat/Long
4	Burlington	34.51-34.80	High Friction Surface Treatment	-	-	-	-	-	Yes	-	Yes	41.771901, -72.951576	41.77432, -72.947794
4	Burlington	35.43-35.56	High Friction Surface Treatment	-	-	-	-	-	Yes	-	-	41.777964, -72.937099	41.778849, -72.934986
7	Sharon	64.01-64.28	Resurfacing & High Friction Surface Treatment	2.25"	Yes	-	2.25"	-	Yes	-	Yes	41.869109, -73.366838	41.871385, -73.364718
39	Danbury	3.99-4.10	Resurfacing & High Friction Surface Treatment	2.25"	Yes	Yes	2.25"	-	Yes	-	-	41.443838, -73.507468	41.444491, -73.509085
41	Sharon	4.64-4.74	Resurfacing & High Friction Surface Treatment	3.00"	Yes	Yes	2.00"	1.00"	Yes	-	-	41.880612, -73.476669	41.881783, -73.475733
44	Salisbury	1.59-1.73	High Friction Surface Treatment	-	-	-	-	-	Yes	-	Yes	41.95679, -73.46552	41.956505, -73.463053
63	Litchfield	35.50-35.63	Resurfacing & High Friction Surface Treatment	2.25"	-	Yes	2.25"	-	-	Yes	-	41.754703, -73.191791	41.756261, -73.193115
67	Roxbury	7.14-7.29	Resurfacing & High Friction Surface Treatment	2.25"	Yes	Yes	2.25"	-	Yes	-	-	41.567401, -73.326645	41.567994, -73.324669
167	Farmington	0.12-0.24	High Friction Surface Treatment	-	-	-	-	-	Yes	-	Yes	41.75809, -72.880967	41.7597, -72.880143
167	Avon	0.95-1.05	High Friction Surface Treatment	-	-	-	-	-	Yes	-	-	41.766205, -72.870014	41.766939, -72.86846
167	Avon	3.34-3.44	High Friction Surface Treatment	-	-	-	-	-	Yes	-	-	41.794551, -72.861535	41.795858, -72.861392
183	Winchester	11.02-11.12	High Friction Surface Treatment	-	-	-	-	-	-	Yes	-	41.940656, -73.086727	41.94172, -73.087809
315	Simsbury	0.80-0.92	Resurfacing & High Friction Surface Treatment	2.25"	Yes	-	2.25"	-	-	Yes	-	41.898631, -72.774797	41.900078, -72.774057
343	Sharon	0.86-1.00	Resurfacing & High Friction Surface Treatment	2.25"	Yes	Yes	2.25"	-	-	Yes	-	41.874421, -73.488603	41.874463, -73.486052
540	East Granby	0.45-0.81	High Friction Surface Treatment	-	-	-	-	-	Yes	-	Yes	41.921642, -72.754791	41.921332, -72.74966
540	East Granby	0.95-1.06	High Friction Surface Treatment	-	-	-	-	-	Yes	-	-	41.919621, -72.74815	41.918513, -72.746801

NOTES:
RESURFACED ROAD SEGMENTS REQUIRE A 30 DAY CURE TIME BETWEEN PLACEMENT OF NEW ASPHALT AND INSTALLATION OF HFST

THE DESIGN APPEARS TO CONFORM TO APPLICABLE CRITERIA. APPROVAL IS NOT TO BE CONSTRUED TO MEAN THAT ALL ASPECTS OF THE DESIGN HAVE BEEN PERSONALLY CHECKED BY THE UNDERSIGNED.

TRANSPORTATION PRINCIPAL ENGINEER _____